

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY WHITE & GEROR, 1846 E. Broadway, Tucson, Arizona
(Address)

LEASE Duncan-White #2 WELL NO. 2 UNIT F S 34 T 13S R 33E
DATE WORK PERFORMED Jan. 7, 1957 POOL Lazy J

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

A 75 sack bottom hole plug was spotted to cover the exposed perforations, a 50 sack cement plug was spotted in the bottom of the 8-5/8 casing as only 4200' of 5 1/2 casing was recovered. A 25 sack cement plug was spotted at 1040', which was the stub of the 8-5/8 casing. A 50 sack cement plug was spotted at the bottom of the surface and a 5 sack plug in the top with a 4" marker 5' above the ground.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____	_____	_____

(Company)

OIL CONSERVATION COMMISSION

Name Smith, Hugh
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Alan Antwell
Position Agent
Company White & Geror