

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Carl J. Westlund, Inc.		Address W. Pickett, 909 Midland Savings Bldg., Midland, Texas			
Lease Hondo-State	Well No. 1	Unit Letter P	Section 21	Township 14-S	Range 33-E
Date Work Performed June 1, 1961	Pool Saunders			County Lea	

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☒ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

June 1, 1961, acidized w/2000 gal., perforations 9840-9852. Removed bridge plug at 9865'. Put well back to pumping June 5, 1961. Perforations now open are 9882-9898 in addition to 9840-52. Well now pumping 33 BOPD, 70 BWP.

Witnessed by James W. Brown	Position Vice President	Company Carl J. Westlund, Inc.
---------------------------------------	-----------------------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA					
D F Elev. 4229	T D 10,025	P B T D 9869	Producing Interval 9882-98, 9840-52	Completion Date 6-5-61	
Tubing Diameter 2-3/8"	Tubing Depth 9638	Oil String Diameter 4 1/2"	Oil String Depth 10,025		
Perforated Interval(s) 9882-98 & 9840-52					



Open Hole Interval	Producing Formation(s) Permo-Penn.
--------------------	--

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover	2-17-61	22	33	0	1500	-
After Workover	6-5-61	33	50	70	1500	-

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name 
Title Agent	Position Agent
Date JUL 10 1961	Company Carl J. Westlund, Inc.