

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SEP 17 1969

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name Maud Saunders
3. Address of Operator Box 670, Hobbs, New Mexico 88240	9. Well No. 2
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 34 TOWNSHIP 14-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Saunders Permian Penn
15. Elevation (Show whether DF, RT, CR, etc.) 4200' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Plugged and Abandoned

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10,000' TD, 9932' PB.

Pulled tubing. Ran CI BP and set at 7820'. Cut and recovered 7" casing from 5235'. Spotted 30 sack cement plug from 5250' to 5150', across 7" casing stub at 5235'. Spotted 40 sack cement plug from 4280' to 4180', across 9-5/8" casing shoe at 4229'. Cut and recovered 9-5/8" casing from 813'. Spotted 55 sack cement plug from 863' to 763', across 9-5/8" casing stub at 813'. Spotted 75 sack cement plug from 350' to 250', across 13-3/8" casing shoe at 312'. Spotted 40 sack cement plug from 50' to surface. Installed dry hole marker and cleaned location. Plugged and abandoned September 16, 1969.

(Pumping unit and casing is stored on location pending final disposition).

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY

C. E. MACE

SIGNED **C. E. MACE** TITLE **Area Petroleum Engineer**

DATE **September 17, 1969**

APPROVED BY **John W. Runyan** TITLE **Area Petroleum Engineer**

DATE **September 17, 1969**

CONDITION OF APPROVAL, IF ANY: