RICE Engineering Corporation

122 WEST TAYLOR TELEPHONE (505) 393-9174

May 12, 1988

New Mexico Oil Conservation Division P. O. Box 1980 Hobbs, New Mexico 88240

Re: Chevron USA, Inc.
Maud Saunders #4 SWD
Unit L-Sec. 34-T14S-R33E

Gentlemen:

Attached is Form C-103 and chart from the annulus integrity test for the above well. The annulus was displaced with treated fresh water before setting the packer at 4071'. Injection was resumed following this test.

Yours very truly,

RICE ENGINEERING CORPORATION

L.B. Goodheart Division Manager

JH/jp

Attachments