

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-963	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Re-entry		7. Unit Agreement Name
2. Name of Operator Sage Oil Company		8. Farm or Lease Name State "SA"
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, N M 88240		9. Well No. 1
4. Location of Well UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 35 TOWNSHIP 14S RANGE 33E N.M.P.M.		10. Field and Pool, or Wildcat Under Saunders Permian
15. Elevation (Show whether DF, RT, GR, etc.) 4190 DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/10/78 Ran tubing & spotted 50 sacks cement on top of 8 5/8" casing stub at 480'. Loaded hole with mud. Pulled tubing up & spotted 80 sacks cement across 13 3/8" casing shoe at 306'.

8/11/78 Tagged top of plug at 200'. Set 10 sack plug at surface with regulation marker.

Above plugging operations witnessed by Mr. Nathan Clegg.

Location is ready for inspection.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Wm. H. Hols</i></u>	TITLE Agent	DATE 10/23/78
APPROVED BY <u><i>G. A. Stutzman</i></u>	TITLE OIL & GAS INSPECTOR	DATE DEC 17 1980
CONDITIONS OF APPROVAL, IF ANY:		