

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company MURPHY H. BAXTER				Address 507 MIDLAND NAT'L BANK BLDG., MIDLAND, TEXAS			
Lease LOWE-STATE	Well No. 1	Unit Letter 0	Section 20	Township 12-N	Range 34-E		
Date Work Performed 12-6-62	Pool UNDESIGNATED			County LEA			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Set 25 sacks cement at the following depths: 10,383', 9702', 5548', 4153' (base of 8-5/8" casing), 1579' (top of 8-5/8" casing), 397' (base of 13-3/8" casing), and at the top of the 13-3/8" surface casing. A steel plate was welded in top of 13-3/8" casing and a 4" x 4' pipe marker was welded on top.

Witnessed by J. K. JONES	Position DRILLING FOREMAN	Company MURPHY H. BAXTER
-----------------------------	------------------------------	-----------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval			Producing Formation(s)	

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>John W. Remyer</i>	Name <i>W. U. Remyer</i>
Title	Position PETROLEUM ENGINEER
Date DEC 8 1962	Company MURPHY H. BAXTER