

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
<b>E-1233-E</b>	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>TEXACO Inc.</b>		8. Farm or Lease Name <b>New Mexico 'CX' State</b>
3. Address of Operator <b>P. O. Box 728, Hobbs, New Mexico 88240</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>F</b> , <b>2080</b> FEET FROM THE <b>West</b> LINE AND <b>1880</b> FEET FROM THE <b>North</b> LINE, SECTION <b>34</b> TOWNSHIP <b>12-S</b> RANGE <b>34-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Ranger Lake Penn</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4173' (DF)</b>		12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data



NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well has been plugged and abandoned as listed below:

1. Loaded hole with mud.
2. Spotted 50 sx cement plug from 9298 to 10322'.
3. Spotted 25 sx plug at surface. No casing recovered.
4. Set 4" marker extending 4' above ground level and clean location. Plug and abandon complete December 9, 1969.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE <b>Assistant District Superintendent</b>	DATE <b>December 9, 1969</b>
APPROVED BY 	TITLE <b>Geologist</b>	DATE <b>APR 20 1970</b>
CONDITION OF APPROVAL, IF ANY:		