NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well,

•	s of the Commission.	d by an agent of the Commission. See additional
	Indicate Nature of Report by Checking B	elow
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON REPAIRING WELL
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOMPLETION OPERATION	REPORT ON (Other)
	May 16, 1955	Hobbs New Mex
Following is a report on the work	done and the results obtained under the heading	noted above at the
Stanolind Oil and Gas	Company	Lois Wingerd
	by , Well No 1	
T 12-S , R. 37-E , NMPM., G1	adiola Pool,	Lea Count
The Dates of this work were as folows:	May 1, 1955 to May 3, 19	15.5
Notice of intention to do the work ((was not) submitted on Form C-102 on	, 19
and approval of the proposed plan		(Cross out incorrect words)
	LED ACCOUNT OF WORK DONE AND RES	ULTS OBTAINED
This form is filed t May 3, 1955.	o correct casing size as in	dicated on C-103 dated
On May 1, 1954, we r	on 1.1871 of 8.5/88 cooling a	set at 4500' with staging
3% gel plus 100 sack 30 hours, tested cas No drop in pressure.	an 4487' of 8-5/8" casing a Cemented in two stages; 1st s neat; 2nd Stage: 150 sa ing before drilling plug wi After drilling plug teste drop in pressure. Resumed	cks meat. After WOC for th 1000 psi for 30 minutes. d casing with 1000 psi
3% gel plus 100 sack 30 hours, tested cas No drop in pressure.	s neat; 2nd Stage: 150 saing before drilling plug wi After drilling plug testedwop in pressure. Resumed	cks meat. After WOC for th 1000 psi for 30 minutes. d casing with 1000 psi
8% gel plus 100 sack 30 hours, tested cas No drop in pressure. for 30 minutes. No Witnessed by Ca. Da. Harvey. (Name)	s neat; 2nd Stage: 150 saing before drilling plug wi After drilling plug tested pop in pressure. Resumed Stanolind Oil and Ga	cks neat. After WOC for the 1000 psi for 30 minutes. d casing with 1000 psi operations. S. Company Hd Rebt.
8% gel plus 100 sack 30 hours, tested cas No drop in pressure. for 30 minutes. No Witnessed by	s neat; 2nd Stage: 150 saing before drilling plug wi After drilling plug tested app in pressure. Resumed Stanolind Oil and Garage (Company) I hereby certify to the best of my Name	cks meat. After WOC for the 1000 psi for 30 minutes. It casing with 1000 psi operations. S. Company Hd. Rabt. That the information given above is true and complete knowledge.
8% gel plus 100 sack 30 hours, tested cas No drop in pressure. for 30 minutes. No Witnessed by	s neat; 2nd Stage: 150 saing before drilling plug wi After drilling plug tested apop in pressure. Resumed Stanolind Oil and Ga (Company) I hereby certify to the best of my Name	cks neat. After WOC for the 1000 psi for 30 minutes. d casing with 1000 psi operations. S. Company Hd Rebt.

.		
•	,	
	,	
	÷	
		•
	÷	
	•	· • •
: .		