

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Tri-Service Drilling Company			Address Box 1785, Midland, Texas			
Lease Mary F. Hyatt	Well No. 1	Unit Letter B	Section 10	Township 13-S	Range 37-E	
Date Work Performed 2-4-60	Pool Wildcat			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

50 sacks cement 12,600'-12,730'
 50 sacks cement 9625'-9750'
 50 sacks cement 4495'-4630'
 Shot pipe 3435' (Dia Log) - would not come loose
 Shot pipe 2300' (Dia Log) - would not come loose
 Shot pipe 1200' - pulled 8-8/8" casing
 25 sacks cement 1200'
 10 sacks cement top of 13-2/8" casing

Witnessed by R. S. Bond	Position Contact Representative	Company Tri-Service Drilling Company
-----------------------------------	---	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>Leslie V. Clement</i>	Name <i>R. S. Bond</i>
Title <i>Oil Conservation Commissioner</i>	Position Contact Representative
Date <i>FEB 1 1960</i>	Company Tri-Service Drilling Company