NUMBER OF CO	GA5			NEW MEXICO		No -		COMMISSIO	HOB	^B FORM C-103 (Rov SC 55) 10 34 AM 5 64		
OPERATOR			(Subn	nit to appropria	· -	انو هر 	as per Co	mmission Rule	1106)	34 AM Su		
Name of Com		abot	Corporatio		P.	P. O. Box 4395, Midland, Texas						
	In Low	• "B"		Well No. Ui	nit Lette	r Section	Township	13-8	Range	37-E		
Date Work Pe	rformed		Pool	ng-Wolfen	ų.		County	Los	L			
				S A REPORT OF			te block)					
Beginning Drilling Operations Casing Test and Cer						ment Job Ther (Explain):						
	Plugging Remedial Work Detailed account of work done, nature and quantity of materials used, a						Temporarily abandon					
						1.5		e ng ga si (La sura () La sura ()				
Witnessed by	Witnessed by Howard Mauk Position Field						sup't. Company Cabot Corporation					
			FILL IN BE	LOW FOR REM			PORTS O	NLY				
D F Elev.	F Elev. T D			ORIGINAL PBTD			Producing Interval		Compl	Completion Date		
Tubing Diame			Tubing Depth		Oil Str	ing Diamer		Oil String	Depth			
Perforated Int	erval(s)					- <u>1</u>						
Open Hole Interval						Producing Formation(s)						
		<u></u>		RESULTS (DF WOR	KOVER						
Test	Date o Test		Oil Production BPD		iction	Water P	roduction PD	GOR Cubic feet/Bl	Gi bl	as Well Potential MCFPD		
Before Workover												
After Workover		····										
		SERVAT		۹	I her to th	eby certify e best of n	that the in y knowledg	formation given e.	above is	true and complete		
pproved by						Name Parti C. Chini						
itle Engineer in an i						Position Blst. Prod. Sup't.						
Date		y 1 1	at .		Comp	Company Cabot Corporation						

in the second second

and the second second

and a state of the second s