NUMBER OF COPIES A		-							
SANTA FE	BUTION	NEW	MEXICO O	IL CON	ISERY	ATION CO	MMISSION	FORM C-103	
USGS LANDOFFICE TRANSPORTER OIL TRANSPORTER OIL TRANSPORTER OIL									
PRORATION OFFICE	GA3	(Submit to	appropriate D	istrict (Office a		ission Rule 110		
me of Company	y			Address	-0 4	_	1 Fit 3	43	
	erporation	Well	No. Init			drews, Township		nge	
ease M. M. Harr	ris	well	····	Letter	8	12-S		38-1	
te Work Perfor	med.	Cladiola De	mand an		C	County	-		
March 30,	1903		EPORT OF: (Check at	propriat				
Beginning 1	Orilling Operations		Test and Cem			Other (Ex	blain):		
Plugging	J -	Remedi	al Work		T/A	Report			
Detailed account of work done, nature and quantity of materials used, and results obtained.									
			:	. 18			· · · · · · · · · · · · · · · · · · ·		
Witnessed by Position				Company					
C. R. Kor	34118	FILL IN BELOW	Production	DIAL W	ORK RI		Corporation LY	R	
		FIEL IN BELOW	ORIGINAL						
D F Elev.	Elev. T D		PBTD			Producing Interval		Completion Date	
Tubing Diamete	er	Tubing Depth		Oil Strin	g Diame	eter	Oil String I	Depth	
Perforated Inte	rval(s)	<u> </u>	•	I					
Open Hole Interval					Producing Formation(s)				
			RESULTS O	F WOR	OVER				
Test	Date of Test	Oil Production BPD	Gas Produ MCFP			Production BPD	GOR Cubic feet/Bb	Gas Well Potentia	
Before Workover									
After Workover							f	above is true and compl	
	OIL CONSERV	ATION COMMISSION		I her	eby cert: e best o	f my knowled	ge.	above is true and compl	
Approved by				Name			46		
Title				Posit					
					Area Predaction Hanager Company				
Date /				Gui	LE 01.1	Cerpose	Lon		