

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

rig&2cc: OCC, Hobbs
cc: Regional Office
cc: file
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Henry A. Harris
9. Well No. 1
10. Field and Pool, or Wildcat Gladiola Devonian
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Plug and Abandon
2. Name of Operator SINCLAIR OIL & GAS COMPANY
3. Address of Operator F. O. Box 1920, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM East LINE, SECTION 18 TOWNSHIP 12S RANGE 38E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3868'GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4-10-68 Set C.I. Plug @ 11,900' and spotted 2 sacks cement 11,890-11,900'. Filled hole w/heavy mud laden material.
- 5-3-68 Shot 5-1/2"OD casing off @ 5195' and pulled. Spotted 25 sacks cement plug in top of 5-1/2"OD casing stubb 5124-5195'.
- 5-6-68 Spotted cement plug, 25 sacks 4436-4494' in bottom of 9-5/8"OD casing. Spotted 10 sacks cement plug in surface casing and cellar, installed regulation dry hole marker, cleaned and levelled location.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John W. Runyan TITLE Superintendent DATE 5-7-68

APPROVED BY John W. Runyan TITLE Geologist DATE MAY 27 1968

CONDITIONS OF APPROVAL, IF ANY: