

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANITARY	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

N. MEXICO OIL CONSERVATION COMMISSIO.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR OPERATIONS TO BE LATER REOPENED OR TAKEN TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL OR REOPEN FOR SUCH PURPOSES.		5a. Indicate Type of Lease State ☐ Fee ☒
1. Name of Operator Amerada Hess Corporation		7. Unit Agreement Name
2. Address of Operator Drawer D, Monument, NM 88265		8. Form of Lease Name Bronco S.W.D.
3. Location of Well UNIT LETTER J 1982.75 FEET FROM THE South LINE AND 1414.7 FEET FROM East LINE, SECTION 11 TOWNSHIP 13 S. RANGE 38 E. N.M.P.M.		9. Well No. 2
11. Elevation (Show whether DF, RT, GR, etc.) 3810' DF		10. Field and Pool, or Valued Bronco
12. County Lea		

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	SUBSEQUENT REPORT OF: PLUG AND ABANDON ☐ CHANGE PLANS ☐ OTHER ☐ REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐ ALTERING CASING ☐ PLUG AND ABANDONMENT ☐ P & A ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

November 28, 1977 - December 7, 1977

Found 5½" casing parted at 558' from surface. Pulled and laid down 5½" csg. Perf 5½" csg at 4581' w/4 shots. Pumped 250 sks cement. Checked top of cement at 4220'. Perf 5½" csg at 4180' w/4 shots and pumped 300 sks cement. Checked top of cement at 3054'. Perf 5½" csg at 2985' w/4 shots and pumped 300 sks cement. Checked top of cement at 1500'. Spotted 125 sks cement at 636'. Pulled tbq to 332' and reversed out 7 bbls. cement. Checked top of cement at 342'. Pressure tested cement plug w/800#, held OK. Perf 8-5/8" csg at 334' w/4 shots and pumped 350 sks cement. Circulated 250 sks cement out 13-3/8" csg and squeezed 100 sks and left 8-5/8" csg full of cement. Checked top of cement at 80'. Removed BOP, cut off 8-5/8" csg at surface. Installed dry hole marker. P&A. Plugging procedures witnessed and approved by Nathan Clegg with New Mexico Oil Conservation Commission.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>E.B. Bunker</u>	TITLE <u>Supv. Admin. Serv.</u>	DATE <u>12-8-77</u>
REMOVED BY <u>Eddie Lean</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>MAY 20 1978</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

1977

OIL CONSERVATION COMM.
MOBBS, N. M.