

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

HOBBS OFFICE O.C.C.  
APR 18 2 30 PM '66

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
State - R-11264

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	NONE
3. Address of Operator	8. Farm or Lease Name
TEXACO Inc.	State of N.M. "BY" NCT-1
4. Location of Well	9. Well No.
UNIT LETTER A, 660 FEET FROM THE North LINE AND 990 FEET FROM	2
THE East LINE, SECTION 35 TOWNSHIP 13-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat
	Lazy "J"
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4219' (D. F.)	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1708.

Total Depth - 9813'  
8 5/8" O. D. Casing Cemented at 4150'

Ran 9792' of 4 1/2" O. D. Casing, 11.60 LB, J-55, NEW, and cemented at 9813' with 450 Sx. Trinity Lite Wate, plus 200 Sx. Lone Star Neat with 4% gel. Plug at 9790'. Job complete 1:00 P. M. April 14, 1966.

Tested 4 1/2" O. D. Casing for 30 minutes with 1500 P. S. I. from 9:00 A. M. to 9:30 A. M. April 16, 1966. Tested O. K. Job complete 9:30 A. M. April 16, 1966.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dan Gillett TITLE Assistant District Superintendent DATE April 18, 1966

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: