

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-22111

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

4. Well Location

Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line

Section

1

Township

14S

Range

33E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4196' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Clean out ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-27-94 - Milled 1" to 9823'. Bottom out in shoe. TOOH. TIH with shoe, 1 joint washpipe, jars, drill collars and tubing. Tagged at 9823'. Started milling. Cut to 9835'. Circulate clean. Shut in.

8-28-94 - Tagged at 9835'. Did not make any hole in 3-1/2 hours. TOOH & changed shoe. TIH. Tagged at 9835'. Made 1' in 1-1/2 hours. Washed over 4' to 9840'. Circulate clean. Shut in.

8-29-94 - Tagged at 9840'. Made 6" with cement, metal and rubber in returns. Quit torqueing. TOOH & recovered out of shoe and washpipe - 3" OD X 1.05' center of CIBP, 2-9/16" Baker EL receptacle seal nipple parted above lugs, crossover, 2-1/16" Baker sliding sleeve, crossover, Baker seal assembly with catch, mandrel of Model N packer, crossover, 8' X 2-1/16" sub, 2-1/16" Baker F nipple, 4" cement plug. Laid down washpipe and shoe and jars. TIH with new 4-3/4" bit, drill collars and tubing. Tagged at 9840'. Drilled and washed cement to 9891'. Drilled CIBP. Lost 10 bbls fluid in perforations 9904-9912'. Drilled out to 9996' (float collar). Circulate clean.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Rusty Klein

TITLE

Production Clerk

DATE 9-6-94

TYPE OR PRINT NAME

Rusty Klein

505-748-1471
TELEPHONE NO.

(This space for State Use)

SEP 12 1994

TITLE

DATE