

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-22326

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
OG-1516

7. Lease Name or Unit Agreement Name

~~Lazy J SWD~~
N.M. "DM" State NCT-1

8. Well No.
1

9. Pool name or Wildcat
Lazy J Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER ☒ (SWD)

2. Name of Operator
Texaco Inc.

3. Address of Operator
P.O. Box 730, Hobbs, NM 88240

4. Well Location
Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line
Section 21 Township 13-S Range 33-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4267' KB, 4254' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Unsuccessful Fishing Job ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

08-26-89 Tubing is standing full. Attempted to pump into well to 500 psi--unsuccessful.
08-27-89 MIRU pulling unit. Installed BOP. TOH w/IPC tbg and pkr.
08-29-89 TIH w/3-7/8" Kutrite shoe, washpipe, DC and 2-3/8" workstring.
08-30-89 Tag'd fish (Loc-set pkr) @ 9452'. Cut 9452-55'. TOH. Recovered 1' of
Loc-set mandrel. TIH with Kutrite shoe and BHA.
08-31-89 Wash 9452-59'. Plugged shoe. TOH. Recovered formation and iron (csg).
TIH with Kutrite shoe and BHA.
09-01-89 Tag'd @ 9452'. Washed down from 9452-58' (formation in returns).
Plugged washpipe. TOH.
09-02-89 Removed BOP. Flanged up well. Rig down pulling unit. SWD well shut-in.
This well will be evaluated for recompletion or P&A before December 1, 1989.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. A. Head TITLE Area Manager DATE 10-13-89

TYPE OR PRINT NAME J. A. Head

TELEPHONE NO. (505) 393-7191

(This space for State Use)

Orig. Signed by,
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

OCT 23 1989

REC-4

OCT 20 1967

12
FROM