

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K 5920	
7. Unit Agreement Name	
N. A.	
8. Farm or Lease Name	
State	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Wildcat	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator
Freeport Oil Company
3. Address of Operator
1005 V & J Tower, Midland, Texas 79701
4. Location of Well
UNIT LETTER J, 2310 FEET FROM THE East LINE AND 1650 FEET FROM THE South LINE, SECTION 11 TOWNSHIP 13S RANGE 36E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
3947' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was plugged and abandoned June 11, 1969, with Class "H" cement. Plugs as follows:

Devonian	14,260 - 14,173'	25 sxs.
Top Miss.	12,950 - 12,863'	25 sxs.
Top Atoka	12,095 - 12,008'	25 sxs.
Top Wolfcamp	9,625 - 9,538'	25 sxs.
Top Abo	8,120 - 8,033'	25 sxs.
Top Glorietta	6,060 - 5,973'	25 sxs.
San Andres	4,525 - 4,438'	25 sxs. (Base of 8-5/8" casing)
Surface		10 sxs.

8 fts. of 12-3/4" 38# casing set at 406' and 110 fts. of 8-5/8" 32# & 24# casing set at 4525' was left in the hole.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Don L. Sparks TITLE Division Engineer DATE Jan. 30, 1970

APPROVED BY John W. Runyan TITLE Geologist DATE Jan. 30, 1970

CONDITIONS OF APPROVAL, IF ANY: