| NO. OF COPIES RECEIVED | 1 | Form C-103 |
|--------------------------------|---|---|
| | - | Supersedes Old C-102 and C-103 |
| DISTRIBUTION | NEW MEXICO OIL CONSERVATION COMMISSION | Effective 1-1-65 |
| SANTA FE | | |
| FILE | - | 5a. Indicate Type of Lease |
| U.S.G.S. | - | State 🚺 🛛 🛛 Fee |
| LAND OFFICE | | 5. State Oil & Gas Lease No. |
| OPERATOR | | E-3013 |
| | | |
| DO NOT USE THIS FORM FOR PR | RY NOTICES AND REPORTS ON WELLS oposals to drill or to deepen or plug back to a different reservoir. tion for permit -" (form C-101) for such proposals.) | |
| | TION FOR PERMIT (FORM C-TOT) FOR SUCH PROPOSALD. | 7. Unit Agreement Name |
| l. GAS GAS | | |
| WELL WELL | OTHER- | 8. Farm or Lease Name |
| 2. Name of Operator | | N. M. (86) State |
| Lone Star Producing Co | anpany | 9. Well No. |
| 3. Address of Operator | | 1 |
| Box 4815, Midland, Texas 79701 | | 10. Field and Pool, or Wildcat |
| 4. Location of Well | 1080 | Tres Papalotes |
| UNIT LETTER | 1980 FEET FROM THE North LINE AND 1980 FEET | FROM |
| | | |
| West LINE, SECT | 10N 33 TOWNSHIP 14 S RANGE 34 B | имрм. Д//////////////////////////////////// |
| | | 12. County |
| | 15. Elevation (Show whether DF, RT, GR, etc.) | |
| \mathcal{A} | 4112.2' Ground | |
| 16. Check | Appropriate Box To Indicate Nature of Notice, Report of | or Other Data |
| | INTENTION TO: SUBSEQ | UENT REPORT OF: |
| NOTICE OF | INTERTION TO: | |
| | PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING |
| PERFORM REMEDIAL WORK | COMMENCE DRILLING OPNS. | PLUG AND ABANDONMENT |
| TEMPORARILY ABANDON | | |
| PULL OR ALTER CASING | CHANGE PLANS CASING TEST AND CEMENT JUB | |
| | | |
| | 1 11 | |
| OTHER | Operations (Clearly state all pertinent details, and give pertinent dates, inc | |

17. Describe Proposed or Completed Op work) SEE RULE 1103.

Moran Oil Producing and Drilling Company spudded 17-1/2" surface hole at 9:00 A.M., May 1, 1970. 13-3/8" O.D., 48#, H-40 casing was set at 415', cemented with 450 sacks of Class "H" cement with 2% calcium chloride. Cement circulated. Waited on cement 18 hours. Tested 13-3/8" O.D. casing and BOP equipment to 800 psi water pressure for 30 minutes with no pressure loss.

Resumed drilling 11" hole.

| 18. I hereby certify that the information above is true and comple | ete to the best of my knowledge and belief. | |
|--|---|------------------|
| SIGNED Ca R amor | TITLE Dist. Prod. Superintendent | DATE May 5, 1970 |
| APPROVED BY ALCONDITIONS OF APPROVAL, IF ANY: | TITLE JUPERVISOR DISTINCE | MAY 1 1 1970 |