

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-5450	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Lone Star Producing Company		8. Farm or Lease Name N. M. (87) State
3. Address of Operator Box 4815, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER K , 1874 FEET FROM THE West LINE AND 2086 FEET FROM THE South LINE, SECTION 33 TOWNSHIP 14 S RANGE 34 E NMPM.		10. Field and Pool, or Wildcat Tres Papalotes (Penn)
15. Elevation (Show whether DF, RT, GR, etc.) 4107.4' G.L.		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Marcum Drilling Company spudded 17-1/2" surface hole at 11:30 A.M., December 12, 1970. 13-3/8" O.D., 48#, H-40 casing was set at 445', cemented with 450 sacks of Class "H" cement with 2% calcium chloride. Cement circulated. Waited on cement 18 hours. Tested 13-3/8" O.D. casing and BOP equipment to 1000 psi water pressure for 30 minutes with no pressure loss.

Resumed drilling 11" hole.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *J. R. Ramsey* TITLE District Prod. Superintendent DATE January 18, 1971
APPROVED BY *J. R. Ramsey* TITLE SUPERVISOR DISTRICT DATE JAN 20 1971
CONDITIONS OF APPROVAL, IF ANY: