The following are tabulations of the deviation surveys taken on the BTA Oil Producers' 7113 JV-D Marie #1, Unit "O", Section 29, T-14-S, R-34-E, Lea County, New Mexico:

	Inclination
Depth	Degrees
900'	$\frac{1}{4^{\circ}}$
1,490'	1/20
1,915'	1/40
2,400'	3/4 ^ċ
3,083'	1/20
3,450'	3/40
3,790'	1-1/40
4,125'	10
4,418'	00
4,618'	0 ⁰
5,075'	1/2 ⁰
5,250'	1/2°
5,857'	1/20
6,331'	10
6,871'	lo
7,452'	<u>1</u> 0
7,975'	1-1/40
8,727'	1-1/20
9,463'	2-1/2 ⁰
-	

I certify that the above information is true and correct to the best of my knowledge.

Ŕ. D. Boyce

For BTA Oil Producers

Subscribed and sworn to before me this 11th day of April, 1973.

Janis Jones (/

Notary Public in and for Midland County, Texas