

COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-6326	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: Abandoned Well		7. Unit Agreement Name	
2. Name of Operator R. L. Burns Corp.		8. Farm or Lease Name State '32'	
3. Address of Operator 3990 First National Bank Building, Dallas, Texas 75202		9. Well No. 1	
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>14 S</u> RANGE <u>32E</u> NMPM.		10. Field and Pool, or Wildcat Penn	
15. Elevation (Show whether DF, RT, GR, etc.) 4328.7' Gr		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set 375' 13-3/8" 45# csg. Cemented with 425 sx Cl "C" cement with 2% CaCl₂. Waited 17 hrs. Tested w/ 1000# psi for 1 hour. Hole filled with water, held OK.
- Set 3986.39' 8-5/8" 32# csg. Cemented with 400 sx 50:50 Litewater cement with 2% CaCl₂. Waited 21 hrs & tested with 1000# for 1 hour. Hole filled with water, held OK.
- Stuck bit trying to drill out cement on intermediate string; could not retrieve fish, made decision to abandon.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wayne Carlton TITLE Production Engineer DATE December 8, 1975

APPROVED BY _____ TITLE _____ DATE December 8, 1975

CONDITIONS OF APPROVAL, IF ANY: