NO. OF COPIES PECETYED			Supersedes Old
DISTRIBUTION			C-102 and C-103
SAHTA FE	NEA WE	XICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FRE			gan commission and co
U.S.G.S.			5a. Indicate Type of Leave
LAND OFFICE			State Free X
CPERATOR .			5. State OH & Gaz Leane No.
			- Letter Control Control
TOO NOT USE THIS FORM	7. Unit Agreement Same		
1. 이 (()	· - -1		7. Out represent raine
with (A) with (отнея-		6. Form or Leuse Name
Z, Nime of Operator			· ·
J & R Oil Company			Lewis Et Al
1. Address of Operator AC25 North Pinck Chrosts Abilance Torrag 70603			
4525 North First Street; Abilene, Texas 79603			#1 10. Field and Pool, or Wildox
4. Lecation of Well			387:1 d = a +
UNIT LETTER G	1650 FEET FROM	THE North LINE AND 1353 FEET	MIIGGE WILLIAM
THE East LINE	E. SECTION 23 T	DIVERSHIP 13S RANGE 38E NA	10 mm
		Dr. hr. ch	12. County
	11111111111111111111111111111111111111	ion (Show whether DF, RT, GK, etc.)	. \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
		3804 KB	Lea (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
16. C	heck Appropriate Box	To Indicate Nature of Notice, Report or	Other Data
	OF INTENTION TO:	SUBSEQUI	ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG	ARD ABANDON REMEDIAL WORK	ALTERING CASING
TEMPERARILY ABAHOON		COMMENCE DRILLING OPHS.	PLUG AKO ABAHDONMENT
PULL OR ALTER CASING	CHAR	GE PLANS CASING TEST AND CEMENT JOB X	rm
		OTHER	LJ
OTHER			
			ding actimated dute of starting any proposed
17. Describe Proposed of Comp work) SEE RULE 1103.	leted Operations (Clearly stat	e all pertinent details, and give pertinent dates, inclu	uring estimated data by stateing any property
	rom 3631 (surface	casing seat) to a depth of 4625'.	Ran fluid volume survey
		howed the volume of the hole from	
		f an 11" hole with no wash-outs.	
		&C casing on bottom with guide s	
above shoe, follow	ved by 534' of new	8-5/8" - 24#, S-80, ST&C casing	, followed by 2587' of new
8-5/8" - 24#, K-5	5. ST&C casing.	Set casing at 4625 and cemented v	with 1170 sacks of 'Lite'
		onite, and $1/4\#$ Flocele per sack)	
		with 2% Calcium Chloride (Yield	
		e shown by fluid survey required	
		ement set for 24 hrs Drilled o	
to casing shoe. P	ressured up casin	g to 1500 p.s.i. for 30 min Pre	ssure did not decrease.
Resumed drilling	7-7/8" hole below	8-5/8" casing.	
_ /	/ // //		
18, I hereby certify that the info	orgation above in true and cor	uplete to the best of my knowledge and belief.	
1 MA	14. 1. X		
X7/(9)	WW	V. President	DAYE 4/4/77
TENED.	The state of the s		
	Orig. Signed by	·	
	Jerry Sexton	TITLE	BATE
PPHOYED DY	Dist 1, Supv.		
COMPITIONS OF APPROVAL,	IP ANYI		

RECEIVED

APR7 1977

CL Committee Committee Russis, fil all