

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator COTTON PETROLEUM CORPORATION		8. Farm or Lease Name LOWE LAND
3. Address of Operator 420 Wall Towers West, Midland, Texas, 79701		9. Well No. 1
4. Location of Well UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM <u>East</u> THE <u>26</u> LINE, SECTION <u>13 S</u> TOWNSHIP <u>37 E</u> RANGE <u>37 E</u> NMPM.		10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3859' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-15-79 Set CIBP @ 10,011'. Capped w/35' cement. Attempted to cut 4½" casing @ 8102' - unsuccessful.
6-16-79 Cut 4½" casing @ 6515'. POH & LD 4½" casing.
6-18-79 RIH w/2 3/8" tubing to 8030'.
6-19-79 Spotted 100' cement plugs @ 8030', 6565', 6070', 4750' & 2200'. Spotted 10 sx plug @ surface. Welded on steel cap and installed DHM. All plugs spotted w/9.5 ppg mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>L. G. Langley</u>	(L. G. Langley)	TITLE <u>Division Production Manager</u>	DATE <u>6-25-79</u>
APPROVED BY <u>Eddie Seay</u>		TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>JAN 19 1981</u>
CONDITIONS OF APPROVAL, IF ANY:			