

Well LORETTA D. LOWE #1

Date JUNE 8, 1980



Test #	Items Tested	Pressure Pt.	Pressure	Minutes Held	Results
1	Blind rams with inside manifold valves and inside kill-line valve closed	gauge connection	2000#	10 min	Loss, repressure No visible leak, close outside manifold valves
2	"	"	2000#		Loss, repressure, leak through outside manifold valve motor side
3	"	"	2000#		Same leak operate
4	"	"	2000#		Leak, Tool Pusher will replace
5	Pipe rams with inside kill-line valve closed, inside chokeline valve closed	down drill pipe	2000#	10 min	No visible leak
6	Hydril with inside chokeline valve closed and inside kill-line valve closed	"	600#	10 min	No visible leak after Loss & repressure
7	casing	"	0#		Leaking through valve well head
8	"	"	0#		Leak same tighten
9	"	"	500#	10 min	No visible leak