

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
LG3818 & L5371

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator R. L. Burns Corp.	8. Farm or Lease Name State '32'
3. Address of Operator 5110 First International Bldg., Dallas, Texas 75270	9. Well No. #1
4. Location of Well UNIT LETTER <u>E</u> , 1980 FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>13S</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or Wildcat Baum (Upper Penn)
15. Elevation (Show whether DF, RT, GR, etc.) 4260.7' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

14 joints 13-3/8", 48#, ST&C casing set at 429.12', 17 1/2" hole, cemented with 450 sx.  
Waited on cement 15 hours, pressure tested to 700#, held okay.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Michael J. Protholz</u>	TITLE <u>Engineering Supervisor</u>	DATE <u>8-26-80</u>
Orig. Signed by <u>John Runyan</u> Geologist	TITLE _____	DATE <u>SEP 2 1980</u>
APPROVED BY _____	DATE _____	
CONDITIONS OF APPROVAL, IF ANY:		