

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-4945	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator MWJ PRODUCING COMPANY		8. Farm or Lease Name Saunders 16 State	
3. Address of Operator 400 W. Illinois - Suite 1100 Midland, Texas 79701		9. Well No. 1	
4. Location of Well UNIT LETTER <u>I</u> <u>660</u> FEET FROM THE <u>east</u> LINE AND <u>1980</u> FEET FROM THE <u>south</u> LINE, SECTION <u>16</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or Wildcat Saunders Permo Upper Perm	
15. Elevation (Show whether DF, RT, GR, etc.) 4211.5' GL		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

Plug back & prepare to Directionally drill

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

9/2/87: Spotted 75 sx cmt plug thru pump cavity @ 9780'. Cut off 2-3/8" tbg @ .8690'.
9/5/87: Spotted 25 sx cmt plug @ 8452'. Cut off 5-1/2" csg @ 6012'.
9/6/87: Pulled & LD 5-1/2" csg. Spotted 75 sx cmt from 6060-5800'.
9/7-18: Waiting on Rotary.
9/19/87: MI & RU Rotary.
9/20/87: Commenced to re-enter.
10/12/87: Depth 8915'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Pat Drexler TITLE Pat Drexler-Agent DATE 10/12/87

APPROVED BY JERRY SEXTON DISTRICT SUPERVISOR TITLE DATE OCT 15 1987
CONDITIONS OF APPROVAL, IF ANY: