

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISIC
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-72

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. V-267	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> OTHER- Dry		7. Unit Agreement Name
2. Name of Operator San Juan Oil Company		8. Farm or Lease Name State 27
3. Address of Operator 705 S. Elgin, Tulsa, OK 74120		9. Well No. #1
4. Location of Well UNIT LETTER M 660 FEET FROM THE West LINE AND 810 FEET FROM THE South LINE, SECTION 27 TOWNSHIP 14S RANGE 34E NMPM.		10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 4108 GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging operations commenced 11-3-81 and were completed on 11-7-81.

Set CIBP @ 10,352'. Dump bail 37' of cement on top of bridge plug. Cut 5½" casing @ 6640' and POOH. Spot 50 sxs Class H cement from 6531-6694'. Tag top of plug @ 6531'. Spot 35 sxs Class H cement from 5800-5993'. Spot 50 sxs Class H cmt from 4448-4635'. Tag cement @ 4448'. Spot 35 sxs Class H cement from 1700-1800'. Cut off casing head. Spot 5 sxs cement @ surface. Weld on steel plate and 5' marker with legal description. Hole was full of 3% KCl water.

Note: Location has been cleaned of all junk and debris. Pits will be levelled and restored within 30 days. We will notify you when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Susan Lany TITLE Production Technician DATE 11-12-81
APPROVED BY A. H. Hartman TITLE OIL & GAS INSPECTOR DATE JUL 12 1982
CONDITIONS OF APPROVAL, IF ANY: