STATE OF NEW MEXICO

ENERGY AND MAN TOALS DEPARTMENT

	OIL CONSERVATION DIVIS	ION .
DISTRUTUTION	P. O. BOX 2088	Form C-103 :
SANTAPE	SANTA FE, NEW MEXICO 8750	Revised 10-1-78
FILE	SANTA LE NEW MEXICO 6750	5a. Indicate Type of Lasse
U.S.O.S.		State X Fee
LAND OFFICE		5. State Otl 6 Gus Lesse No.
DPERATOR		
		V-1412
SUNDRY N	NOTICES AND REPORTS ON WELLS ALS TO PHILL ON TO DELPTH OF PLUE BALL TO A DIFFERENT P FOR PERMIT - " FORM C-101) FOR SUCH PROPOSALS.)	
(DO NOT USE THIS FORM FOR PROPERTY USE "IMPRICATION F	OR PERMIT =" (FORM C-101) FOR SUCH PROPOSALS.)	
		7, Unit Agreement Name
WELL X WELL	East Bagley Unit	
Name of Operator		8. Farm or Lease Name
Yates Petroleum Corpor	ation	East Bagley Unit
Address of Operator	9. Weil No.	
207 South 4th St., Art	esia, NM 88210	1
Location of Well		10. Field and Pool, c: *iidcat
0 100	O PEET FROM THE North LINE AND 19	80 East Bagley Penn
UNIT LETTER	FEET FROM THE LINE AND	
Fact	6 125	34E (111111111111111111111111111111111111
THE LINE, SECTION _	6 TOWNSHIP 12S RANGE	212 "mon ////////////////////////////////////
mmmmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4204.6' GR	Lea
	7///	
· Check App	propriate Box To Indicate Nature of Notice	e, Report or Other Data
NOTICE OF INTE	ENTION TO:	SUBSEQUENT REPORT OF:
	_1	
ERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
CMPORARILY ABANDON	COMMENCE DRILLIA	IG OPHS. PLUG AND ABANDONMENT
JLL OR ALTER CASING	CHANGE PLANS CASING TEST AND C	KDL THEMES
	OTHER	
OTHER		
. Describe Proposed or Completed Opera	tions (Clearly state all pertinent details, and give pertin	sent dates, including estimated date of starting any proposed
work) SEE HULE 1103.		
Ran 10 joints 13-3/8"	61# J-55 ST&C casing set 416'. 1-	Texas Pattern Guide shoe set 416'.
Insert float set 375'.	Cemented w/400 sx Class "C" + 1/	4# Celloseal + 2% CaCl2. Compressive
strength of cement 125	0 psi in 12 hrs. PD 7:00 PM 12-1-	85. Bumped plug to 1000 psi, re-
	oat held okay. Cement circulated	

Drilled out 3:00 PM 12-2-85. WOC 20 hours. Cut off and welded on flow nipple. Reduced hole to 11". Drilled plug and resumed drilling.

APPROVED BY	Eddie W. Seay Oil & Gas Inspector	71768	DEC 9 - 1985
1 1	. 4	Production Supervisor	12-5-85
18. I hérèby cert	ify that the information above is true and co	omplete to the best of my knowledge and belief.	

DEC 6- 1985

. .