

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-2064	

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Exxon Corporation		8. Farm or Lease Name South Four Lakes Unit
3. Address of Operator P. O. Box 1600, Midland, TX 79702		9. Well No. 8
4. Location of Well UNIT LETTER <u>Lot 1 A</u> 660 FEET FROM THE <u>N</u> LINE AND 990 FEET FROM THE <u>E</u> LINE, SECTION <u>2</u> TOWNSHIP <u>12S</u> RANGE <u>34E</u> RMPM.		10. Field and Pool, or Withcat Four Lakes Devonian
11. Elevation (Show whether DF, RT, GR, etc.) 4150' GR		12. County Lea

10. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1708.

Spud 17 1/2" hole 1-16-86. On 1-17-86 set 13 3/8", 54.5# csg. at 406'. Cemented w/ 500 sx ClC. Circulated to surface. On 1-19-86 (46 hours after cementing) csg. was tested to 1800 psi - OK. Resumed drilling.

On 1-27-86 set 8 5/8", 32 and 24# csg. at 4170'. Cemented with 1600 sx ClC. Circulated to surface. Waited 15 hours and tested csg. to 2000 psi - OK. Resumed drilling 1-28-86.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Melba Kripling TITLE Section Head DATE 2-4-86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE **FEB 6 - 1986**

RECEIVED
FEB -5 1986
OCD
HOBBS OFFICE