

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30037
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-2265
7. Lease Name or Unit Agreement Name Tahoe WA State
8. Well No. 1
9. Pool name or Wildcat Saunders Permo Upper Penn

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>11</u> Township <u>14S</u> Range <u>33E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Acidize perforations <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-20-94 - Moved in and rigged up pulling unit. POOH with pump and rods.  
9-21-94 - POOH with 2-7/8" J-55 tubing. WIH with packer. Tested tubing to 6000#. Set packer at 9700'. Tested packer. Flanged well up. Shut well in.  
9-22-94 - Acidized perforations 9774-9983' (Bough AB, C & D) with 300 gallons of 20% HCL, 2000 gallons 10# brine gel with 3000# rock salt block and ball sealers, 3000 gallons 20% HCL, 2000 gallons of 10# brine gel with 3000# rock salt block and ball sealers and 3000 gallons 20% HCL. Flushed with 2% KCL water. Shut well in.  
9-23-94 - POOH with packer at 9700'. WBIH with mud anchor, perforated joint, seating nipple and tubing anchor. Changed out bad tubing. Flanged up well.  
9-24-94 - Ran pump and rods. Spaced out stroke. Released to production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 9-28-94  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

SEP 30 1994

RECEIVED

SEP 28 1994

OFFICE