COMPANY:

WEST-TEST INC.

CLIENT:

MARALO, INC.

GAUGE NUMBER:

29240

WELL NAME:

DAVIS 15

WELL NUMBER:

1

TEST NUMBER:

97-14-0112

LOCATION:

LEA COUNTY, NEW MEXICO

TEST OPERATOR: 4 BT AND SD

COMMENTS:

TEMPERATURE SURVEY

POSITION 1

GAUGE SERIAL NUMBER