



Reservoir Engineering Services

2:45	38		77			
				Cushion	NONE	Amount _____ ft.
				Cushion		Amount _____ ft.
				Total fluid recovered	1118 ft.	9.9 bbl
				97 ft of	MUD	1.2 BBL
				1021 ft of	GAS CUT OIL	8.7 BBL
				ft of		
				ft of		
				ft of		
				ft of Oil recovered in drill pipe		
				Test was/was not reversed circulated?	WAS TO TEST TANK	
				Recovery		
				Top sample chlorides	2300 PPM CHL	
				Middle Sample chlorides	42.5 API @ 60 DEG/F	
				Bottom Sample chlorides	42.5 API @ 60 DEG/F	

ELF 02/26/11

ABOVE DATE DOES NOT
INDICATE WHEN
CONFIDENTIAL LOGS
WILL BE RELEASED

