

APPROVED

COPY TO

Budget Bureau No. 42-R358.4.  
Approval expires 12-31-60.

JUN 13 1963

(SUBMIT IN TRIPPLICATE)

Land Office **Santa Fe**Lease No. **MM-04401-B**Unit **RECEIVED**

MAY 22 1963

SUNDRY NOTICES AND REPORTS ON WELLS  
U.S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	XX
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 20, 1963

Well No. 1 is located 1980 ft. from N line and 660 ft. from E line of sec. 10  
SE/4 Sec. 10 T-7-S 32-E NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Squyres Pennsylv. Roosevelt New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4474 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**Federal "C" #1:** TD 9637' PBTD 8520'. 13-3/8" @ 300' circ., 8-5/8" @ 3375' w/1500 sx, top cement 991'. 5 1/2" @ 9630' w/500 sx, top cement 6963'. A 50 sx plug was run at TD to cover perforations, hole was loaded w/mud-laden fluid. The 5 1/2" csg. was shot off at 4218' and 20 sx plug placed at stub of 5 1/2". A 20 sx cement plug was placed across shoe of 8-5/8" casing. The 8-5/8" casing was shot at 860' and pulled. A 30 sx cement plug was placed at stub of 8-5/8" csg. A 30 sx cement plug was placed across shoe of 13-3/8" casing. A 20 sx cement plug was placed at surface, and proper permanent U.S.G.S. marker was installed; location cleaned and cleared. Effective date of plugging, 5-1-63.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Campana Petroleum CompanyAddress P.O. Box 1652  
Midland, TexasBy [Signature]  
Agent

Title \_\_\_\_\_