



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau 42-R358.2
Approval expires 12-31-52.

Land Office **Santa Fe**
Lease No. **078183**
Unit **1**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. **1** is located **660** ft. from **5** line and **660** ft. from **5** line of sec. **33**
33 (1/4 section 33)
33 (Twp.) **33** (Meridian)
Midland (Field) **Midland County** (Division) **New Mexico** (Territory)

The elevation of the derrick floor above sea level is _____ ft. **(will be given later)**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Casing Program:

300' Surface Casing

3100' San Andres

6800' Abo

6900' Permian

7400' Mississippian

8100' Granite

13 3/8" cemented at 290', cement circulated to surface.

9 5/8" cemented at 3700' with 1200 sacks.

5 1/2" cemented at 8000' with 500 sacks.

1. Plans and program of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Signal Oil & Gas Company**

Address **214 Central Building**

Midland, Texas

By

Glenn J. Smith

Title

DISTRICT LANDMAN