## INCLINATION REPORT

OPERATOR Nax Wilson ADDRESS \_\_\_\_\_

LEASE (ox WELL NO. 7 FIELD

LOCATION Unit N, Section 33, 7-5-S, R-36-E, Roosevelt County, New Mexico

Depth	Angle Inclination 'degrees)	Displacement	Displacement Accumulated
304 800 1299 1800 1985 2465 2948 3631 3788 4222 4384 4645 4700	1/4 1/2 1/2 1/4 3/4 1/4 3/4 3/4 3/4	1.3376 2.1824 4.3413 4.3587 .8140 6.2880 6.3273 8.9473 1.3659 5.6854 2.1222 3.4191 .7205	1.3376 3.5200 7.8613 12.2200 13.0340 19.3220 25.6493 34.5966 35.9625 41.6479 43.7701 47.1892 47.9097

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Cactus Drilling Company Ken Hedrick XS Title: Unilling Supt.,

Affidavit:

Before me, the undersigned authority, appeared <u>Ken Hedrick</u> known to me to be the person whose name is subscribed herebelow, who, on making deposition, under oath states that he is acting for and in behalf of the operator of the well identified above, and that to the best of his knowledge and belief such well was not intentionally deviated from the true vertical whatsoever.

Ken Hedrich Signature TAffiant's

Sworn and subscribed to in my presence on this the 22nd day of \_\_\_\_\_

February 19 72\_.

Notary Public in and for the County

Notary Public in and for the County of Lea, State of New Mexico MC COMMONS ON EXCERCISE 2017