| NO. OF COPIES RECEIVED DISTRIBUTION SANTA FE | NEW MEXICO OIL CON | SERVATION COMMISSION | - | | |
|---|--|---|--------------------------------|----------|--|
| U.S.G.S. | 1 | 5a. Indicate Type of Lea | ise | | |
| LAND OFFICE | - | State | Fee, 🔀 | | |
| OPERATOR |] | | 5. State Oil & Gas Leas | ;e No. | |
| SUNDR (DO NOT USE THIS FORM FOR PR USE "APPLICAT | RY NOTICES AND REPORTS ON OPOSALS TO DRILL OR TO DEEPEN OR PLUG FION FOR PERMIT -" (FORM C-101) FOR SU | NWELLS BACK TO A DIFFERENT RESERVOIR. ICH PROPOSALS.) | 7. Unit Agreement Name | | |
| OIL GAS WELL | OTHER- Drilling Well | L | , one Agreement Nume | | |
| 2. Name of Operator | | | 8. Farm or Lease Name | | |
| Southern Minerals Corporation | | | M. Setser | | |
| 3. Address of Operator | | | 9. Well No. | | |
| P. O. Box 716 Corpus Christi, Texas | | | 1 | 1 | |
| 4. Location of Well UNIT LETTER FEET FROM THE North Line and FEET FROM. | | | 10. Field and Pool, or Wildcat | | |
| | | | Wildcat | | |
| | on 28 TOWNSHIP 5-SOL | th BANGE 35 East | | | |
| 15. Elevation (Show whether DF, RT, GR, etc.) | | | 12. County | | |
| | 4206.8 Gr. | | Roosevelt | | |
| Check | Appropriate Box To Indicate 1 | Nature of Notice, Report or Ot | her Data | | |
| | NTENTION TO: | | T REPORT OF: | | |
| | | | | | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | REMEDIAL WORK | ALTERING CAS | ING | |
| TETPORARILY ABANDON | | COMMENCE DRILLING OPNS. | PLUG AND ABA! | NDONMENT | |
| | | 1 1 | | | |
| PULL OR ALTER CASING | CHANGE PLANS | CASING TEST AND CEMENT JOB | | | |
| OTHER | CHANGE PLANS | CASING TEST AND CEMENT JOB | | | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

August 5, 1967 Drilled to T.D. of 4800'. Ran logs and DST from 4520' to 5600'. Mr. J. D. Ramey, Oil Conservation Commission District #1 Supervisor, was contacted and issued verbal permission to plug the Wildcat well.

- August 6, 1967 Set 25 sacks cement from 4515'-4600', 25 sacks from 3235'-3320', 25 sacks from 2195'-2280', 25 sacks from 315'-400' and 10 sacks from 0'-30'. Plate welded on top of surface pipe with marker.
- September 26,1967 Pits have been filled and location levelled and cleared of junk.

NOW READY FOR INSPECTION.

| 16. I hereby certify that the information above is true and c | omplete to the best of my knowledge and belief. | |
|---|---|----------------------|
| SIGNED | TITLE Authorized Employee | DATE October 2, 1967 |
| APPROVED BY John W. Rung | An title | |
| CONDITION OF APPROVAL, IF ANY: | | DATE |