

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Energy Reserves Group, Inc.		8. Farm or Lease Name Bledsoe
3. Address of Operator P. O. Drawer 2437, Midland, Texas 79702		9. Well No. 1
4. Location of Well UNIT LETTER <u>H</u> <u>1874</u> FEET FROM THE <u>North</u> LINE AND <u>766</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>6-S</u> RANGE <u>33-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4402.3 G.L.		12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIATION WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

04-14-80: TD 7900'. Ran 4 1/2", 11.6#, & 10.5#, K-55 casing to 7880' and cmt'd. w/400 sax Class "H". Plug down @ 11:15 P.M. on 04-14-80. Hung casing on slips. TOC 6816' by Temperature Survey. WO completion unit.

08-13-80 TD 7900'. PBDT 7868'. Press test 4 1/2" casing to 1500# for 30 min. OK. WOC time was almost 4 months.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. L. Robertson R. L. Robertson TITLE Production Engineer II DATE April 16, 1980

APPROVED BY Jerry Sexton TITLE Dist. L. Supt. DATE AUG 18 1980

CONDITIONS OF APPROVAL, IF ANY: