

FIELD REPORT NO.: 36406E CAPACITY: 6400#
INSTRUMENT NO.: J-371 NUMBER OF REPORTS: 5

Chart indicates severe plugging in final flow to the extent that recorder stylus was damaged.

