STATE OF NEW MEXICO	
ENERGY AND MINERALS DEPARTMENT	
JIL CONSERVATION DIVISION	
DISTICIBUTION P. O. BOX 2088	Form C-103
SANTA FE SANTA FE, NEW MEXICO 87501	Revised 10-1-78
FILE SANTATE, NEW MEXICO 87501	· · · · · · · · · · · · · · · · · · ·
U.S.O.S.	5a. Indicate Type of Lease
LAND OFFICE	State Foo X
OPERATOR	5, State Oil & Gus Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	Annunnun an
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF TO DEFPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -"" (FORM C-101) FOR SUCH PROPOSALS.)	$\chi = \chi =$
	7, Unit Agreement Name
OIL CAB	•
, Nume of Operator	8. Farm or Lease Name
Yates Petroleum Corporation	Durwood XW
Address of Operator	9. Well No.
207 South 4th St., Artesia, NM 88210	2
, Location of Well	10. Field and Pool, or Wildcut
UNIT LETTER 990 FEET FROM THE South LINE AND 1650 FEET FROM	Tomahawk SA
	<b>VI</b> ////////////////////////////////////
East 18 TOWNSHIP 75 RANGE 32E NMPM.	$\qquad \qquad $
	$\boldsymbol{\nabla} (\boldsymbol{M} )\boldsymbol{M} )\boldsymbol{M} \boldsymbol{M} \boldsymbol{M} \boldsymbol{M} \boldsymbol{M} \boldsymbol{M} \boldsymbol{M} \boldsymbol{M} $
11111111111111111111111111111111111111	12. County
()))))))))))))))))))))))))))))))))))))	Roosevelt
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK	ALTENING CASING
COMMENCE DEILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CABING	
OTHER	L

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 26" hole 4:30 PM 5-8-84 with rathole. Set 43' of 20" conductor pipe. Resumed drilling with rotary tools 6:00 PM 5-9-84. Ran 41 joints of 8-5/8" 24# J-55 casing set 1660'. 1-Texas Pattern notched guide shoe set 1660'. Insert float set 1620'. Cemented w/600 sacks Pacesetter Lite w/3% CaCl2. Tailed in w/200 sacks Class "C" 2% CaCl2. Compressive strength of cement - 1250 psi in 12 hours. PD 2:00 PM 5-11-84. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 35 sacks. WOC. Drilled out 2:00 AM 5-12-84. WOC 12 hours. Nippled up and tested to 1000 psi for 30 minutes, OK. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

6. I hereby certify that the information above is true and com	TITLE Production Supervisor	<u>5-15-84</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR ONDITIONS OF APPROVAL, IF ANY:		MAY 17 1984