	-
N. M. OIL CONS. COMMISSION	
P. O. BOX 1980	
HOBBS, NEW MEXICO 88240	_
Form 9–331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	Maljamar Grayburg Unit NM 031571
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
SUNDRY NUTICES AND REFORTS ON WELLS Do not use this form for proposals to drill or to deepen or plug back to a different	Maljamar Grayburg Unit
eservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas	Maljamar Grayburg Unit
well 😾 well 🗀 other	9. WELL NO.
2. NAME OF OPERATOR	21
Chevron U. S. A., Inc. 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Maljamar (Grayburg-San Andres)
P. O. Box 1660 Midland, Texas 79702	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) AT SUBFACE. Unit K, 1980' FSL & 2310' FWL	Sec. 4, T-17-S, R-32-E
AT SURFACE: UNITERVAL: 3859'	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH: 4189'	Lea New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. NA
REPORT, OR OTHER DATA	
	15. ELEVATIONS (SHOW DF, KDB, AND WD) DF 4140'
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
SHOOT OR ACIDIZE	ROU
REPAIR WELL	(NOTE: Report (esuits of a put of exampletion or zone
PULL OR ALTER CASING L L	Lichtange ba folmogla 300 Les 20
	LAN C 1004
ABANDON*	JAN 6 1984
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is o measured and true vertical depths for all markers and zones pertine	lirectionally drilled, give subsurface locations and
Fish & recover stuck tbg. RIH w/pkr. & set @ 3797'. Load backside. Tes Swab test to determine productivity. Tests we written to place #21 back on production as soon POOH w/pkr. NUWH	re positive & a job will be
Work commenced on 12-16-83 & was completed on	12-20-83.
Prior to work, well had been temporarily aband	oned w/stuck tbg. left in hole.
Chevron will contact USGS as soon as job has b on production.	een approved to place back
Subsurface Safety Valve: Mend. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED) /// / / / / / / / /////////////////	DATE 1-5-84
LUNA	DATE
CONDITIONS OF APPROVAMAYANY 9 1984	

Carlabel, NEW MEXICO. See Instructions on Reverse Side

• ·

MAY 1 1 1984 2⁹ HOBBS OFFICE

...