



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 0274061 (h)
Unit Lea

3 16

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Subseq. of Prod</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____ Aug 6 _____, 1962
Groce Mitchell B
Well No. 4 is located 660 ft. from SW line and 1980 ft. from E line of sec. 5
SW 1/4 of SE 1/4 Sec. 5 17 32 MTN
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Maljara Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4086 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Sand jetted notches at 4040', Breakdown pressure 3100#, 4030' Breakdown pressure 2400# and 3894' Breakdown pressure 2700#. Treated notches with 57000# 20-40 sand and 57,000 gallons lease crude with 3000# Mark II Acumite. Max treating pressure 4000#, Minimum Pressure 3000#. 5 Minute SIP 2700#. Average Injection Rate 13.9 BPM.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 427

Hobbs, New Mexico

By L. S. Adams

Title Assistant Superintendent

USGS (3) 124066 (2) WAK File