NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103 (Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS (Submit to appropriate District Office as per Commission Rule 1106) Address 507 Midland Mational Bank Bldg. Name of Company Murphy H. Baxter Midland, Texas Section Township 17-8 Range 32-E Unit Letter Lease Well No. State "18-13" Date Work Performed Pool County Maljamar Lea THIS IS A REPORT OF: (Check appropriate block) Casing Test and Cement Job Beginning Drilling Operations Other (Explain): Remedial Work Plugging Detailed account of work done, nature and quantity of materials used, and results obtained. Ran and cemented 137 joints (4338.4') of 5 1/2" 14# J-55 8RT ST&C new seamless Spang casing @ 4349.0' with 150 sacks of regular 4% Gel cement followed with 1200 gallons of Dowell Cealment. WOC 48 hours. blow out preventers and drilled out sement to 4347'. Tested casing with 1500# for 30 minutes. Casing tested OK. Position Witnessed by Company W. U. Summer Engineer Murphy H. Baxter FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY ORIGINAL WELL DATA DF Elev. TD PBTD Producing Interval Completion Date **Tubing Diameter** Tubing Depth Oil String Diameter Oil String Depth Perforated Interval(s) Open Hole Interval Producing Formation(s) RESULTS OF WORKOVER Oil Production BPD Water Production Gas Production Gas Well Potential Date of GOR Test MCFPD BPD Cubic feet/Bbl MCFPD Before **Vorkover** After Workover I hereby certify that the information given above is true and complete to the best of my knowledge. OIL CONSERVATION COMMISSION Name Approved by Position Date Company

Murphy H. Baxter