MEXICO OIL CONSERVATION COMMISSION

FORM C-103 (Rev 3-55)

			CELLANEOU					•	
		(Submit to ap;	propriate Distric	ci Officias	s per Com	mission R	ule 1106)		
Name of Con	Murphy H.			Addr	ress 507 Mid	Midlai	nd figt'l Texas	Bank Bldg.	
Lease	State "18	8-13"	Well No.	Unit Letter		Township		Range 32-E	
Date Work P	Performed 1-27-59	Pool	Maljamar			County	Lea		
		THI	IS IS A REPORT	OF: (Chec	k approprie		Æ		
Beginn	ning Drilling Opera] Casing Test and				Explain):		
Pluggi	ng		Remedial Work				•		
Detailed acc	count of work don	ne, nature and quant	tity of materials	used, and re	sults obta	ined.			
1000	# for 30 m	ninutes. C	asing test	ted OK.				casing with	
Witnessed by		-	Position		Ţ _c	Company			
		. Lomax	Produc	ction S	Supt.	Murp	hy H. Ba	xter	
		FILLINE	BELOW FOR RE	EMEDIAL V	WORK RE	PORTS ON	VLY		
DF Elev.	Т	D	ORIGIN PBTD	NAL WELL	DATA	Tr. Janing	- -		
						Producing	interval	Completion Date	
Tubing Diame	eter	Tubing Depth		Oil Stri	ing Diamet	:er	Oil String	g Depth	
Perforated In	terval(s)								
Open Hole Inc	1			- 1. , -					
Эреп подели	tervai			Produci	ing Format	ion(s)			
			RESULT	S OF WORL	KOVER				
Test	Date of	Oil Product	tion Gas Pro	roduction	Water Pr	roduction	GOR	Gas Well Potential	
Before Workover	Test	BPD	M C	FPD		PD	Cubic feet/B	Bbl MCFPD	
After Workover									
	OIL CONSER	RVATION COMMISS	ION	I here to the	eby certify e best of m	that the inf ny knowledge	ormation given	above is true and complete	
Approved by	In Alle	Mr hu		Name	1/-)	6/11	n Mi	16.	
itle	700		274	Positi	,	<u> </u>			
Date					Petroleum Engineer				
ate				Compa		rnhu H	Danis on		