M	EXICO OIL CONSE SCELLANEOUS RE priate District Offi	FPORTS (	ON WELLS		3-55) De coc
Company <u><b>Buffelo</b></u>	011 Company A		er Bldg.,	rtesia, No	M Mexico
Lease Retch "A"	Well No. 9	Unit	<u> </u>	T_ <b>_178</b>	R_328
Date work performed	July 29, 1955	_POOL_	Maljamar	·····	
This is a Report of (Cl	ieck appropriate blo	ock)	Result	of Test of Ca	asing Shut-off
Beginning Drilling Operations			Remedial Work		
Plugging			Cther St	nd oil Fra	<u>aturing</u>
Detailed account of wo	rk done nature and	quantity	of materials	s used and r	esults

Detailed account of work done, nature and quantity of materials used and results obtained.

This well was producing 9 BOPD prior to treatment. The well was treated with 15,000 gals. refined oil and 16,000# sand down 2 7/8" OD tubing below a packer and holdown. The initial treating pressure was 4,000 psi. the final pressure was 2200 psi. The maximum injection rate was 8.1 BPM at 3000 psi.

The well potentialed for 26 BOPD' 14 SPN, 28" stroke, GCR 1206.

FILL IN BELOW FOR REMEDIAL	WORK REPORTS ONLY
Original Well Data:	3602-
DF Elev. 4054 TD PBD	
Tbng. Dia. 27/8" Tbng. Depth	Oil String Dia 7" Oil String Depth 3602
Perf. Interval (s)	
Open Hole Interval 4113-3608	Producing Formation (s) San Andrea
RESULTS OF WORKOVER	BEFORE
Date of Test	7/8/55 1 9-5-55
Oil Production, bbls. per day	16 26
Gas Production, Mcf per day	8/0 31.3
Water Production, bbls. per day	
Gas-Oil Ratio, cu. ft. per bbl.	<u> </u>
Gas Well Potential, Mcf per day	
Witnessed by	
	(Company)
Oil Conservation Commiss	ion above is true and complete to the best of my
Off Conservation Commiss	knowledge.
Name	Name Ralph Loran
Title	Position Div. Prod. Supt.
Date	Company Buffalo Oil Company