

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other Instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.
LC 029509 (a)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. UNIT AGREEMENT NAME

mca

2. NAME OF OPERATOR

Continental Oil Company

8. FARM OR LEASE NAME

mca Unit Bty 2

3. ADDRESS OF OPERATOR

Box 460, Hobbs, New Mexico 88240

9. WELL NO.

674. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)**At surface 1980' FSL + 660' FWL, Section 21, T-17S, R-32 E,
Lea County, New Mexico.**10. FIELD AND POOL, OR WILDCAT
**Malgomar Repress
(LISA) Pool**11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA**Sec. 21, T-17S, R-32 E**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4022' DF

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☒(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recombination Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)***Work done:**

Traced 3574-3900 with 20,000 gallons lease crude and
20,000 # sand. Detected holes in casing. Set 5 1/2" OD 17#
casing at 3842. Cemented with 40 sacks Class C cement.
Tested with 750# for 15 minutes. Tested OK. Top of cement
3500 by temperature survey. Acidized 3842-4124 with 6,000
gallons 20% LSTNE acid. Perforated 3707, 3717, 3738, 3743,
3759, 3770, 3774, 3778, 3794, 3797, 3808, 3811, 3824, 3829, with
one hole per foot. Returned well to production.

18. I hereby certify that the foregoing is true and correct.

SIGNED

Robert Gault Adm. Sec. ChiefDATE **4-9-68**

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

USGS-5 Partners-15 File

TITLE

APPROVED**APR 11 1968****J. L. GORDON**
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side