

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME <i>MCA</i>
2. NAME OF OPERATOR <i>CONTINENTAL OIL COMPANY</i>		8. FARM OR LEASE NAME <i>MCA UNIT</i>
3. ADDRESS OF OPERATOR <i>Box 460, Hobbs, N.M. 88240</i>		9. WELL NO. <i>71</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>1980' FSL & 660' FEL OF SEC. 21</i>		10. FIELD AND POOL, OR WILDCAT <i>MAJ. G-SA REPRESS</i>
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>SEC. 21, T-17S, R-32E</i>
15. ELEVATIONS (Show whether DF, RT, GL, etc.)		12. COUNTY OR PARISH <i>LEA</i>
		13. STATE <i>N.M.</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cleaned out to 4147'. Dumped 6 bbls. pea gravel down well. Top of gravel @ 3993'. Cleaned out to 4080' & set Hydromite plug @ 4080'. Ran 2 7/8" orange peel", slotted mud anchor, seating nipple & 126 jts 2 7/8" tubing. Ran rods & pump. Work started 11-3-75, completed 11-6-75. Test before: 51 BO, 419 BW in 24 hrs. Test After: 57 BO, 421 BW in 24 hrs.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE


(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:



*See Instructions on Reverse Side

USGS-5, MCA-4, File