HORNAGE DE OCO 1037 MAR 22 M Form C-103 9: (Revised 3-55) NEW MEXICO OIL CONSERVATION COMMISSION MISCELLANEOUS REPORTS ON WELLS (Submit to appropriate District Office as per Commission Rule 1106) COMPANY Buffalo 011 Company, 203 Carper Building, Artesia, New Mexico (Address) T 178 R 32E WELL NO. 16 UNIT I S 21 LEASE Baish "A" POOL 6-27-56 Nal jamar DATE WORK PERFORMED Results of Test of Casing Shut-off This is a Report of: (Check appropriate block) 🕱 Remedial Work **Beginning Drilling Operations** Other Plugging Detailed account of work done, nature and quantity of materials used and results obtained.

Cleaned out to TD of 4128'. Plugged back with pea-gravel from 4128'-4080', with Cal-Seal from 4080'-4047'.

Fraced down 5¹/₂" OD casing, open hole from 3638'-4047' with 5000 gals. lease crude with sand at 1 lb/gal. Treated at 2000 psi at 8.0 bpm. Recov-ered load oil and well tested at 107 B0 flowing in 18 hrs. on 22/64" choke, TP 340 psi, CP 540 psi, GOR 734. The allowable of this well was increased to 43 BOPD.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. 4041	TD 4145 PBD	4030 Prod. Int. 4030-	Compl Date 6-25-42
Tbng. Dia 2"			Oil String Depth_3635_
Perf Interval (s)	NONE		

Open Hole Interval 3635-4030 Producing Formation (s) Grayburg - San Andres

BEFORE AFTER		
4-6-56 7-10-56		
<u> 16 45 </u>		
2794 2395		
Buffalo Oil Company (Company)		
I hereby certify that the information given above is true and complete to the best of		
ny knowledge Name May & Gurry		
Position Dist. Supt.		
Company Buffalo Oil Company		