

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS 53

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Buffalo Oil Company, 203 Carper Building, Artesia, New Mexico
(Address)

LEASE Baish "A" WELL NO. 10 UNIT E S 22 T 17S R 32E
DATE WORK PERFORMED _____ POOL Maljanar

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☒ Other Temporary abandonment

Detailed account of work done, nature and quantity of materials used and results obtained.

An attempt was made to recomplate this well in the Yates Sand of the Baish Pool. The following work was performed.

A Baker Model "N" bridge plug was set at 2564'. Perforated with Welex F-1 gun at 2514'.

Fractured with 10,000 gals. Devonian water and 2500# sand. CP 500 psi, TP 2500-1900 psi at 4 bpm. Could not recover all of load water. No fluid entry into well bore.

Request permission to temporarily abandon by shutting in well until needed for proposed water flood of Maljanar Pool.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____	(Company) _____	

OIL CONSERVATION COMMISSION

Name _____
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Mark B. Curry
Position Dist. Supt.
Company Buffalo Oil Company

THE COMMISSION MUST BE NOTIFIED
EVERY 6 MONTHS ON FORM C-103
AS TO THE WELL STATUS AND YOUR
FUTURE PLANS FOR THIS WELL.