

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 4106)

COMPANY Buffalo Oil Company, 203 Carper Building, Artesia, New Mexico

(Address)

LEASE Baish "B" WELL NO. 3 UNIT J S 22 T 17S R 32E

DATE WORK PERFORMED 11-56 POOL Maljamar

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☒ Remedial Work

☐ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Pulled tubing and cleaned out from 3964'-4110'. Found junk in hole. Tried to clean up with washover shoe on wash pipe. Recovered large amounts of magnesium and rubber, but could not completely clean up. Hole is fairly tight from 3988'-3996'. Ran tubing and put back on production.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. 3993 TD 4112 PBD _____ Prod. Int. 4112- Compl Date 3-15-45

Tbng. Dia 2" Tbng Depth _____ Oil String Dia 7" Oil String Depth 3586

Perf Interval (s) _____

Open Hole Interval 3586-4112 Producing Formation (s) Grayburg-San Andres

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

9-7-56

12-16-56

Oil Production, bbls. per day

27

38

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

3104

2975

Gas Well Potential, Mcf per day

Witnessed by Larry Duncan

Buffalo Oil Company
(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name _____

Name Max E. Curry

Title _____

Position Dist. Supt.

Date _____

Company Buffalo Oil Company

FOR RECORD ONLY.