

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1421

5. LEASE DESIGNATION AND SERIAL NO.

LC-058697(B)  
C. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME McA Unit Rep.
2. NAME OF OPERATOR Continental Oil Company	8. FARM OR LEASE NAME McA Unit Rep.
3. ADDRESS OF OPERATOR P.O. Box 460, Hobbs, N.M.	9. WELL NO. 140
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FWH + 660' FWH of Sec. 25, T-17S, R-32 E, Lee County, New Mexico.	10. FIELD AND POOL, OR WILDCAT McA Unit Rep.
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, CR, etc.) 4611 B 9.
	11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec. 25, T-17S, R-32 E
	12. COUNTY OR PARISH Lee
	13. STATE N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

Repairing + Deepen 35'

☒

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☐  
☐  
☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

This well was recently shut-in due to a probable casing leak. It is proposed to repair casing leak, cement fill and drill 35' to next TD of 4225'.

Run prod. equipment and place well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

USGS (5) McA (3) File

\*See Instructions on Reverse Side

